1	2	3	4	5	6	7	8

А

All dimensions are in mm except for the thread

6 D10 is [-78µm;+30µm] 20 H8 is [0 µm;+33µm]

A

в

С

D

Е

F

Threading goes toward the chamfer

